

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

K85  
WNW  
1/8-1/4  
0.165 mi.  
870 ft.

SERVICE BOX #40773  
IFO 27-31 STILLWELL AV  
BROOKLYN, NY

NY Spills S105141137  
N/A

Site 1 of 2 in cluster K

Relative:  
Higher

SPILLS:

Actual:  
1 ft.

Name: SERVICE BOX #40773  
Address: IFO 27-31 STILLWELL AV  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 0104675 / 2001-08-27  
Facility ID: 0104675  
Facility Type: ER  
DER Facility ID: 123519  
Site ID: 144931  
DEC Region: 2  
Spill Cause: Unknown  
Spill Class: C4  
SWIS: 2401  
Spill Date: 2001-07-31  
Investigator: JHOCONNE  
Referred To: Not reported  
Reported to Dept: 2001-07-31  
CID: 390  
Water Affected: Not reported  
Spill Source: Unknown  
Spill Notifier: Local Agency  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 2001-07-31  
Spill Record Last Update: 2001-09-07  
Spiller Name: UNKNOWN  
Spiller Company: Unknown  
Spiller Address: UNKNOWN  
Spiller Company: 999  
Contact Name: RICHARD ROACH  
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead\_DEC Field was O'CONNELL CON ED E2MIS REPORT 7-31-01 1gal. of unknown oil found in 10gals. of water in SB-40773. Oil was discovered while #9 was about to do repairs. tag placed and one sample taken. This will be a 24hr. deminimus job. 2100hrs. Due to the nature of the sample( sample will need to be dried for 24hrs. prior to testing) incident will not meet the 24hr. criteria. LSN 01-07834-001; <1ppm - aroclor 1260 8-02-01 1045hrs. <1.0ppm cleanup completed by using coag and double washing structure with slix. Waste product removed with vactor. No sump, drains or oil filled equipment in structure. Tag removed."  
Remarks: "1 GAL ON 10 GALS OF WATER - SAMPLE TAKEN CLEAN UP PENDING LAB RESULTS - CON ED #138614 - NO - SMKOE/FIRE/WATER/PRIVATE PROPERTY"

All Materials:

Site ID: 144931  
Operable Unit ID: 841434  
Operable Unit: 01  
Material ID: 533156  
Material Code: 0066A  
Material Name: unknown petroleum

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Case No.:	Not reported
Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported